Illustrated Parts List - IPL Update

Product Name(s)

525RK

Description of change

1. Uniting of several different article numbers to one.
2. Change of bearing regarding quality.

Comments

Fully exchangeable

Introduced from

Serial number / Date	***Remark***
	Ignition cable 584 82 66-01
	Bearing 506 61 03-01

IPL updates

Page Title	***Ref. no***	***New part no***	***Name***	***Excl. part no.***	***Remark***
Ignition system and clutch	2	584 82 66-01	Ignition cable	576 88 27-01	
Crankshaft	5	506 61 03-01	Bearing	523 07 17-01	