Illustrated Parts List - IPL Update

Product

LEGACY SNOW THROWERS ORIGINALLY EQUIPPED WITH 532188170

Description of change


The old design Bearing Holder is no longer available. Where replacement is required, machines can be updated to the new design as shown below. For each side requiring repair, please order the following:

1: 532420478 Bearing holder - Quantity 1
2: 532411939 Cap - Quantity 1
3: 584299401 Screw - Quantity 2

Comments

Retrofit does not require both sides be updated (one side can remain "old style" while the other is updated).

OLD STYLE



UPDATED STYLE

